

DUTY ON WHICH ENGAGED:

Sequences 3,4,5,6,

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine failed, A/C force landed and struck fence at end of landing run.

COURT OF INQUIRY. INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

Fm/1001/29/10/P/I ^{D-14}

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~
~~Failure of two rocker arm bracket securing bolts.~~

17. Forced Landing 7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~41. Hitting obstructions.~~

26. Engine trouble accident 26

RECORDED BY

DATE

CHECKED BY

DATE