

DUTY ON WHICH ENGAGED: Solo practice on sequences	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:		
6,7,8,10,17. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine sputtered on recovery from spin, pupil attempted forced landing, overshot and struck fence.	DATE: COMPOSITION: FM AUTILIA	of pour to fee fen	
	RECOMMENDATIONS:		
PRIMARY CAUSE: 32. Pilot error.			
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Log book endorsed.		
SECONDARY CAUSE OR CONTRIBUTING FACTORS: 14. Misuse of controls.			
54. Engine failure in the air. 29. Overshooting runway.		RECORDED BY DATE	Ξ
		CHECKED BY DATE	<u> </u>
	·)