Ų	PILOT	OTHERS	28 45 45 64 55 63		SEFRAME		AND ORE	scripto of			NE FAI		7 6
OF A	UNI 9 E.F.T	.S.	CA COM.	U S PLA	ACE		ACCIDE	NTS			43 IIME]		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
`~ F	St. Catha	rines	1	-		M.A.		···········			00-39-		Z WEUTHE
⊢	A/C TYPE	35 13		No.		^	CRASH CAT.	3	SE	ME	DAY	NIGHT	10101/32
	Tiger	Moth NAME	RA	NK	3956 No.	DUTY		INJUI	RIES		SEA	RIOUS	
YPE OF ENGINE	Wilson,				R188280	PP	Ni L.					ARD No.	S E S O U S S A LE CO U S A LE
-	TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPO FORI	RT SERIAL M No.	DAT	- 1	NIGHT	ON TY		TOTAL	LAST	TTI . [/ 45 /
	Tiger Mot G. Major	h 3956 S	Seriously				11131	NIGITI	DUAL	SOLO	DUAL SOL	_O 6 MOS.	10101/28/
GORY	G. Major	2420/00						- ;		- -			GH OF SAN
						No. & D		REPOR		FIL		DATE	

	· • • • • • • • • • • • • • • • • • • •)						
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:								
Solo practice. Sequence 7-8-9.									
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	D-14 D-14 MARIE MARIE D-14 D-14)						
When landing drifted to left,	COMPOSITION:	1307 MAN WE	i						
landed and bounced. A/C started to	FILL		1						
swerve to right, applied left rudder			,						
and brake to stop the swing and threw the A/C violently on port	RECOMMENDATIONS:								
wheel.	Pupil to be given more dual on correcting for drift								
)	before further solo.								
4. Harsh use of brakes.									
1. Others)						
7	ACTION TAKEN:)						
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Pilot's log book endorsed.								
)	S		-'						
			,						
, accomplish of the control of the c)						
SECONDARY CAUSE OR CONTRIBUTING FACTORS: 61. Swinging on landing.)						
35. Cross winds and gusts.		RECORDED BY DATE	-)						
and Eners									
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41		CHECKED BY DATE	ر -						
)))))))))))						