

DUTY ON WHICH ENGAGED:

Formation flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MVLT

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot of 5652 taxied into tail of 5631 which was stationary.

DATE:

COMPOSITION:

TCA/107 ✓
TCA/110

RECOMMENDATIONS:

PRIMARY CAUSE:

3. Hitting other A/C.

9. collisions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed - Retarded one course.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

62. Taxing too fast.

RECORDED BY

DATE

CHECKED BY

DATE