

DUTY ON WHICH ENGAGED:

Solo practice on sequences 6,7,8.

COURT OF INQUIRY, INVESTIGATING OFFICER

D-14

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Student landed with slight drift and ground loop developed. Recovery action was not taken soon enough and ground loop speeded up causing collapse of U/C.

DATE:

COMPOSITION:

LG/PSS/VSS ←

RECOMMENDATIONS:

Student given more dual instruction.

PRIMARY CAUSE:

~~38. Ground loop.~~

2. Sweung 2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Inexperience".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

25. Inexperience.

34. U/C Strain 4

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____