

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																				
TYPE OF A/C																	TYPE OF ENGINE																	CATEGORY																																	
PILOT																	OTHERS																	AIRFRAME FAILURE																	ENGINE FAILURE																
CAUSES OF ACCIDENTS																																																																			
UNIT #10 E.F.T.S. Pendleton										COM. #3 TC					PLACE M.A.										DATE 19.4.43					TIME 0815																																					
A/C TYPE T/Moth										No. 5001-D					CRASH CAT. C 1					SE X		ME		DAY X			NIGHT																																								
T/Moth										5881					C 1					X				X																																											
NAME										RANK					No.					DUTY					INJURIES					SERIOUS																																					
Baggs, H.G.										Sgt R141241					FI					Nil					FATAL		INJURY																																								
McBride, R.W.										PO J22283					FI					Nil																																															
Richardson, J.D.										LAC R164529					PP					Nil																																															
Nutbrown, W.E.										LAC R171360					PP					Nil																																															
TYPE A/F & ENGINE										No.					EXTENT OF DAMAGE					REPORT FORM					SERIAL No.					DATE					HOURS FLOWN BY PILOTS																																
T/Moth #5001										Serious																				INST.		NIGHT		ON TYPE				TOTAL				LAST 6 MOS																									
G/Major 7831/35675 Nil.																																		DUAL		SOLO		DUAL		SOLO																											
T/Moth #5881										Serious																																																									
G/Major 1431/89272 Nil.																																																																			
SIGNAL No. & DATE										UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE																																					
A.497										19.4.43																																																									
NATURE OF ACCIDENT																																																																			

Handwritten scribble or signature across the top right section of the form.

Handwritten checkmark in the 'SERIOUS' column.

DUTY ON WHICH ENGAGED:

5001 - check pupil out on sequences
3,6,7,8,10,12,15,16.
5881 - check pupil out on circuits,

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxiing A/C 5001 between two rows of parked A/C on the tarmac, caught wing tip of above A/C on the propellor of A/C 5881 which was parked with the engine idling.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MULET

DATE:

TCA/PCT
TCA/AA

D-14

COMPOSITION:

RECOMMENDATIONS:

That A/C are not to be taxied in confined quarters without wing men.

PRIMARY CAUSE:

3. ~~Hitting other aircraft.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

24. Carelessness.

RECORDED BY

DATE

CHECKED BY

DATE