

31	JU.	30	TECH.	29	DISOB.	28	NEG/INCE	27	INEXP/INCE	26	MISCEL.	25	INSTRUCT.	24	FLT CONTR.	23	OTHERS	22	PRIMARY	21	FL. CONTS.	20	MOV. SURFS.	19	STAB. SURFS.	18	W. STRUTS	17	LAND GEAR	16	FLOATS	15	FUSE. OR HULL	14	TAIL SKID OR W.	13	ENGINE MOUNT.	12	MISCEL.	11	UND/TD	10	PRIMARY	9	FUEL SYS.	8	COOL SYS.	7	IGNIT. SYS.	6	LUP/N SYS.	5	ENG. STR.	4	AIRSCREW A.	3	ENG. CONTS.	2	MISCEL.	1	UND/TD																																							
3	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
PILOT		OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																														
CAUSES OF ACCIDENTS																																																																																																				
UNIT		COM.					PLACE										DATE		TIME																																																																																	
Patricia Bay, B.C.		WAC					Patricia Bay Aerodrome										5.4.43		1140																																																																																	
A/C TYPE		No.					CRASH CAT.					SE		ME		DAY		NIGHT																																																																																		
Lysander IIIA		2410					R					X				X																																																																																				
NAME					RANK		No.		DUTY		INJURIES					SERIOUS																																																																																				
Moore, H.O.					Sgt		1218757		P		Nil					FATAL		INJURY																																																																																		
Gavin, J.L.					LAC		968602		Drogue Opr.		Nil							1																																																																																		
Hempsall, L.F.					LAC		P147386		Control Radio Opr.		Slightly																																																																																									
																				CARD SERIAL No.																																																																																
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE			REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																							
Lysander IIIA #2410				Seriously									INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																																	
Mercury XX 24167/S102416				Slight											DUAL SOLO		DUAL SOLO																																																																																			
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																																
A.283 5.4.43																																																																																																				
NATURE OF ACCIDENT																																																																																																				

MISCELLANEOUS CAUSES
 FLIGHT STAGE OF
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 INJURY
 360
 RNF
 2
 1

HAND.O.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND/TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 INJURY
 360
 RNF
 2
 1

DUTY ON WHICH ENGAGED:

Drogue towing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxiing stbd brake failed to respond correctly. Pilot attempted to swing A/C away from Control Trailer by use of motor, but failed to do so.

DATE:

700/11/1 ✓

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~2. Hitting obstructions.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~62. Taxiing too fast.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____