\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	PILOT OTHERS A				AIRFRAME FAILURE					ENGINE FAILURE			
PE OF A	UNIT#11	PLACE					DATE 7.5.43 TIME 1205 H.Q. FILE 1100-46-88				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
1	Cap de la Madeleine #3 TC A/C TYPE Finch II			^{No.} 4688		CRASH C.1/2		Ş <u>E</u>	ME	DAY	NIGHT	M - S C EL ORE JAK	
L	NAME RA			NK NO. DUTY				RIES		SE	ERIOUS	O E C C C C C C C C C C C C C C C C C C	
PE OF ENGINE					171256	PP	Nil				CARD RIAL NO.	S O U S SYLAR	
1	TYPE A/F No. EXTENT			REPORT 5		DAT	F	но	URS FLOWN BY P		Y PILOTS		1 / 8/
CATEGORY	Finch #4688 Seriously Kinner 6189/1538 Nil		FORM	ORM No.		1	Night-	DUAL 28	-		LAST 6 MOS	T A G E 41 GH	
	SIGNAL NO & DATE UNIT NO & DAT			TE	E COM. No. & DATE REPO			REPOR	RT FILE		.E	DATE	

DUTY ON WHICH ENGAGED: Seq. 6,7,8.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D.14 #11
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Praked harshly on landing and	DATE: COMPOSITION: LS ANT PSA / PEM/UBI
nosed up, after failing to keep	COMPOSITION:
straight.	
	RECOMMENDATIONS:
PRIMARY CAUSE:	
32. Filot error	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Log Book endorsed "error of judgment"
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
38. Ground loop 36. Nosing up	RECORDED BY DATE
20. Mostuf wh	
	CHECKED BY DATE