DESTRUCTION OTHERS	SIRES SIRES SE SERVICE SE SERVICE SE			ENGIL		Solito Transfer
UNIT No.7 B.&.G.S.	AUSES O	F AC	CIDENTS	DATE 27-5-4	43 TIME 1720	P P P P P P P P P P P P P P P P P P P
Paulson, Man. #2	No. 1579	C	RASH AT. C 1	SE ME	DAY NIGHT	S WEW,
	/S R122838	Р	Nil	RIES	SERIOUS FATAL INJURY	
Adams, J.P.H.	C1 R187844	OC	Nil		CARD SERIAL NO.	S OLY
TYPE A/F No EXTENT	REPORT SERIAL	DATE	но	URS FLOWN BY	/ PILOTS	o landing
Lysander III 1579 Slight	FORM No.	JA. C	INST, NIGHT	ON TYPE	TOTAL LAST DUAL SOLO 6 MOS	
à Mercury XX 24225 Nil			34 18	:20 177	104 584	1 m 4/2/4
	DATE COM	, No. & DA	TE REPO	RT FIL	E DATE	

,) /)) / /)))))	· · · · · · · · · · · · · · · · · · ·					
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER					
G.3 Gunnery exercise.	OR COMMANDING OFFICER'S REPORT: D-14 # 7.					
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: $D = I + I + I + I + I + I + I + I + I + I$					
Pilot made a normal landing. On	COMPOSITION: CONCLUSIONS OF A.I.B. (975)					
turning off at end of runway A/C	D.14 action was sufficient. There is					
swung around, port wheel ran into	no satisfactory evidence as to the con-					
ditch, A/C nosed up.	dition of the runway. Investigating					
)	RECOMMENDATIONS: Officer & C.O. state aerodrome partially serviceable. However, it is felt that					
) PRIMARY CAUSE:	satisfactory evidence should have been					
32. Pilot error.	given as to the nature of the u/s of the					
) of filor error.	runway & whether or not the pilot knew or should have known of this unservice-					
)	ability. As apparently the u/s portion)					
)	ACTION TAKEN: was flagged there was an error in judg- (A) DISCIPLINARY (B) TECHNICAL (C) OTHER ment on the part of					
)	NIL the pilot.					
1)					
))					
secondary cause or contributing factors: 1. Bad surface.of aerodrome.						
35. Cross winds and gusts.	RECORDED BY DATE)					
36. Nosing up.						
) R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE)					
_) _) _) _ ; _) _) _) _) _)						