

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 9 B&G School Mont Joli	COM. 3	PLACE M.A.	DATE 14-6-43	TIME 1420
A/C TYPE Battle I		NO. 1633	CRASH CAT. C	H.Q. FILE 1100-16-33
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

7
4
2
1
7
4
2
1

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Murray, J.R.	F/S	R108568	P.	NIL.	NO.	DATE
Fallon, J.J. Aus.	Lac.	414546	AG	NIL.	146	14-6
					D 14 (REVISED)	
					NO.	CHECKED
					3	<input checked="" type="checkbox"/>
					#5	

MONTH

4
2
1

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Merlin 111	8209/3165	NIL.					
		47	40	34	1	397	125

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52

RAF
M N
INJURY
2RD
5

PURPOSE OF FLIGHT:

Scheduled splash exercise.

TECHNICAL OFFICER'S REPORT:

Tube failure.

LUC/LTB

NATURE OF ACCIDENT:

Stbd tire blew causing A/C to swing to stbd on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~43. Tire trouble.~~

SWUNG

2

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

TYRE BURST

37

ACTION TAKEN:

NIL.