

ACCIDENT CLASSIFICATION

UNIT 9 E.F.T.S. St. Catharines		COM. 1	PLACE Lot 65, Conc.2 Twnshp Niagara, Ont.		DATE 6-6-43	TIME 1545		
A/C TYPE Tiger Moth		NO. 8857	CRASH CAT. C1½	S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL Chambers, F.E.		RANK Lac.	NUMBER R155286	DUTY PP	INJURIES NIL.		SIGNAL	
							NO. DATE	
							D 14 (REVISED)	
							NO. CHECKED	
							4 ✓	
							#25	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Tiger Moth 8857 Slightly G/Major 2452/39295 NIL.			INST.	NIGHT	ON TYPE		TOTAL	
			SOLO	DUAL	SOLO	DUAL		
			10	4	30	37	30	37

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3rd
5
N

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Solo practice on seq. 22.

NATURE OF ACCIDENT:

Engine stopped while doing aerobatics. Pilot carried out a forced landing.

TECHNICAL OFFICER'S REPORT:

Nil.

FB/12/2/1001/2 MC/1001/2

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

32. Pilot error.

SECONDARY OR CONTRIBUTORY FACTORS:

14. Misuse of controls

ACTION TAKEN:

Log book endorsed. Extra duties.