

TYPE OF A/C		UNIT No.10 E.F.T.S.		COM.	PLACE		DATE 1-7-43	TIME 1600	COMMAND		
		Pendleton, Ont.		# 3	M.A.		H.Q. FILE 1100-43-82				
TYPE OF UNIT		A/C TYPE		NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT	MONTH	
		Tiger Moth		4382	C 2	X		X			
CATEGORY		PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		STAGE OF FLIGHT
		Brunet, J.P.G.		LAC	R194079	PP	Nil		NO.	DATE	
D										2-7	TAXYING
C											TAKE-OFF
B											STATRY
A											INJ.
D											INJURY
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF
D											RAF
C											RAF
B											RAF
A											RAF

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Circuits and landings

Nil LH/11/11

NATURE OF ACCIDENT:

Pupil levelled off approx. 10' high,  
stalled and contacted ground violently on wing tip and landing gear. Recovery covered with throttle and landing was completed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~39. Flattening out too soon~~

*F. Heavy*

4

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error~~

ACTION TAKEN:

Nil