

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 19 E.F.T.S. Viriden	COM. 2	PLACE M.A.	DATE 20-9-43	TIME 1430
A/C TYPE TIGER MOTH 82C			H.Q. FILE 1100-12-64	
NO. 1264		CRASH CAT. "C"6	S.E. x	M.E.
			DAY x	NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Floyd, R.E.	LAC	F196678	PP	Uninj.	No. A.194	DATE 20-9
					D 14 (REVISED)	
					No. 4	CHECKED <input checked="" type="checkbox"/>
					#39	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Gipsy Major IC	332651/89183 Nil	-	-	-	8	-	8

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

First solo

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

On first solo landed heavily and bounced. Failed to correct for the bounce and the a/c struck on one wing tip and nosed over on its back.

LH/1 5442

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~40. Heavy landing - flying into grounds.~~

4. Heavy

4

SECONDARY OR CONTRIBUTORY FACTORS:

~~37. Overturning.~~

ACTION TAKEN:

Nil