

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagotville		COM. E	PLACE St.Honore		DATE 11-10-43	TIME 1430		
A/C TYPE HURRICANE XII A		No. BW877	CRASH CAT. "C" 5		S.E. x	M.E.	DAY x	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Libbey, C.C.		F/S	R124918	P	Uninj.		No. A.355	DATE 11-10
							D 14 (REVISED)	
							No. 5	CHECK'D <input checked="" type="checkbox"/>
							#8	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Packard Merlin A-3618		seriously		INST.	NIGHT	ON TYPE		TOTAL
				SOLO	DUAL	SOLO	DUAL	
				48	18	6	-	429 145

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKEOFF
FLIGHT
STABILITY
FATAL
INJURY
3RD
5
M 2

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Formation flying.

NATURE OF ACCIDENT:

Engine failed when a/c was over St. Honore and pilot was blinded by smoke and force landed, wheels up, in middle of aerodrome.

TECHNICAL OFFICER'S REPORT:

Oil starvation of main bearings. As oil was still available in a/c tank, believe oil pump failed or some line clogged or failed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LB/7012/E 5/01/11/1/10/10

CLASSIFICATION:

~~54. Engine failure in the air - 17~~

Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

Engine Trouble - Accident
26

ACTION TAKEN:

Nil