

ACCIDENT CLASSIFICATION

UNIT	128 (F) Sqdn	COM	E	PLACE	R.C.A.F. STATION TORBAY		DATE	21-11-43	TIME	1615			
					H.Q. FILE	1100-57-74							
A/C TYPE	HURRICANE XII			No.	5714	CRASH CAT.	"C"3	S.E.	X	M.E.	DAY	X	NIGHT
PERSONNEL	Gellatly, D.G.		RANK	P/O	NUMBER	J29646	DUTY	P	INJURIES		UNinj.		
				SIGNAL		No.	A.48	DATE	21-11				
				D 14 (REVISED)		No.	#1	CHECKED	<input checked="" type="checkbox"/>				
										#9			
ENGINE	Packard Merlin 29		ENGINE NUMBER (S)	19548/A44631 NIL		HOURS FLOWN BY PILOTS							
				INST.	NIGHT	ON TYPE		TOTAL					
				52	19	SOLO	DUAL	SOLO	DUAL	SOLO	DUAL		
						186	Nil	406	117				

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
LANDING
TAXIING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3rd
5
M

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Circuits & Landings.

KTL. 20/11/50 -

NATURE OF ACCIDENT:

The pilot landed a few feet short of runway 260 causing both tires to blow out and bending the oleo legs and undercarriage.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~30. Undershooting runway.~~ 3
3 Undershot

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot Error.~~

ACTION TAKEN:

Pilots Log Book Endorsed. "Error of Judgment"