

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 7 (B.R.) Sgdn	COM. W	PLACE Alliford Bay, B.C.	DATE 31-5-44	TIME 2310
A/C TYPE CATILINA IV		NO. JX212	CRASH CAT. "D"	H.Q. FILE 1300-JX212
S.E.	M.E.	DAY	NIGHT	
	X		X	

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
					NO.	DATE
					No sig	
					D 14 (REVISED)	
					NO.	CHECKED
					I	✓

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Twin Wasp R183 -92	41508/b/21475 Nil 41516-B/21483 Nil	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STABTY  
FATAL  
INJ.  
INJURY

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF W 2

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

N.A

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

Breaching gear was knocked from under-  
neath hull by Shop Mule.

Causing damage to port chine forward  
Hole torn in Hull at Port Beaching  
gear attachment point. Port wing  
tip float damaged.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

7. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: