



PURPOSE OF FLIGHT:

) Drogue towing.

TECHNICAL OFFICER'S REPORT:

40C/ANT/0115

Coating of rubber from tire head on stbd wheel as from overheating ~~XXX~~ of brake drum.

NATURE OF ACCIDENT:

) Stbd tire blowout on landing causing a/c to swing with the result port tire blewout also causing a/c to slow up suddenly and go up on nose.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

43. ~~Tire trouble.~~

2 Swing

SECONDARY OR CONTRIBUTORY FACTORS:

37 Tyre Burst

ACTION TAKEN:

NIL