

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT Routine Navigation Training Flight. NATURE OF ACCIDENT: Both aircraft crashed following an apparent COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: collision. FINDINGS: SUMMARY No. 2386 CAUSE: Mid air collision. RECOMMENDATIONS: Under the provision of C.A.P. 100, Sec. 1. it is an offence for a pilot to join with, or interfere with, a formation or single a/c without prior arrangement and authorization of form F.17 It is noted, as in the present case, pilot of a/c which joined in breach of above page .of C.A.P.100 may allow that a/c to remain in formation for some tim() without discouraging it. This would not appear to be an offence under para. 28a. Yet it would seem to the CLASSIFICATION: 26. Collision in the air. I.O. that at some point, in absence of discouragement the pilot of the a/c which has been joined accepts the formation and thus would be participant in a formation which has not been authorized. SECONDARY OR CONTRIBUTORY FACTORS: See Summary Wo. 2386 for Notes. ACTION TAKEN: R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K, P, 5051