



PURPOSE OF FLIGHT:

Routine Training Flight.

NATURE OF ACCIDENT:

A/C struck power cables and landed in Moira River.

CLASSIFICATION:

22. Collision Obstr.

SECONDARY OR CONTRIBUTORY FACTORS:

42. Unauthorized low flying.

TECHNICAL OFFICER'S REPORT:

Nil. ILCO/POL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2391

CAUSE: A/C indulged in low flying contrary to regs. striking H.T. cables and after breaking same dove into river fatally injuring occupants.

RECOMMENDATIONS: That this river crossing of H.E. high tension cable be marked on local maps.

CONCLUSIONS OF A.I.B.: A case of unauthorized low flying.

ACTION TAKEN:

Nil.