

	333333333333	* * * • • • •	4
PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT: 1700/10	L/XOV/XCH	4
A/E test.		VCA	
NATURE OF ACCIDENT:	NIL TOO PCH XOV	ХСП	-
			-
Following am a/c which landed in the centre of the runway and was taxiing	COURT OF INQUIRY OR INVESTIGATING O	FFICER'S REPORT:	
clear of runway, pilot elected to la	FINDINGS: CIMMA		
on right side. Strip of runway was	nu clear	4	7
of all obstructions and pilot toucher	d		-
) down and ran alongedge to almost a s	top.		-
Had not noticed a tractor and grader	- -		د
that was stopped about 5 feet from the	he		باسم دن-
edge of the strip. There was no red			3
flam to attract pilots attention and tower's radio was unserviceable. Nose	the		3
) of a/c obstructed view of the tractor	r until	^	_
CLASSIFICATION: it was too late to use	brakino		į.
action to avoid hitting	g it with)
) wing tip	5)
) 9. Collisions.			
SECONDARY OR CONTRIBUTORY FACTORS:			
	ACTION TAKEN:)
	11 November 1)
	Logged.)
R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051			-
H. Q. 865-L 20		C. C. LTD. 7084-43	
-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		ر