

ACCIDENT CLASSIFICATION

UNIT RCAF Detch
Suffield

COM.

REF. NO.

PLACE

3 SPTS, Calgary

DATE 22-6-54

TIME 1505

H.Q. FILE 1100-45-8

A/C TYPE:

LYBANDER II

NO.

458

CRASH CAT.

NCN

S.E.

X

M.E.

DAY

X

NIGHT

TYPE OF A/C

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

MELLAND, C.E.

F/O

C39152

P

Uninj.

NO.

DATE

BARRETT, A.H.

WO2

10081

PASS

Uninj.

T23

23-6

D 14 (REVISED)

NO.

1

CHECKED

✓

#6

MONTH

TYPE OF UNIT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

STAGE OF FLIGHT

ENGINE

ENGINE NUMBER (S)

Perseus XII

2053/29025 slight

HOURS FLOWN BY PILOTS

INST.

NIGHT

ON TYPE

TOTAL

-

-

230


30

1097

140

CATEGORY

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Ferry flight.

TECHNICAL OFFICER'S REPORT:

NIL

LS/PSS/UTB/

SR

LS/PSS/XGN

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

A/C landed and ran for 150' when suddenly port wheel grabbed, causing a/c to ground loop, and in doing so, stbd wheel struck the ditch along runway and stbd wheel blew out and stbd u/c boom was shorn off causing stbd wing and tail mainplane to be extensively damaged on striking ground. A/C ground looped on landing and ran off runway.

CLASSIFICATION:

7. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL