



PURPOSE OF FLIGHT:

Nav. exercise No. 1

NATURE OF ACCIDENT:

Engine failed on take-off. Pilot unable to maintain height unable to climb or gain single engine speed. A/C was maintained in air until it had cleared small village, then pilot forced landed in cleared field with wheels retracted.

CLASSIFICATION:

15. Forced land.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble-Accident.

TECHNICAL OFFICER'S REPORT:

Fuel pump failed and caused an almost complete stoppage in fuel flow to the engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

OFM/AOP/ES/PM/NK/O/UOK/B ✓

ACTION TAKEN:

Nil.