

PURPOSE OF FLIGHT:

Ferrying a/c.

NATURE OF ACCIDENT:

Dinghy swamped while towing a/c.
Apparently confusion in signals
between a/c and Boat.

TECHNICAL OFFICER'S REPORT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

EDGERTON, P. R259074 AC1 W/C Injured.