

DUTY ON WHICH ENGAGED: Unauthorized flight.	OR COMMANDING OFFICER'S REPORT: FM/ATO/POMOBO
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Forced landed in a peer field se that he could render assistance to crashed Finch 230. The brakes were applied harshly and the A/C overturned.	DATE: 19-10-40 to 29-10-40  COMPOSITION: President S/L J.L. Hurlay.  Member F/O H.L. Kay  Member F/O J.B. Williamson.  RECOMMENDATIONS:
PRIMARY CAUSE: Disobedience of orders.	More rigid control of pupil and instructor flying which may be obtained by introducts of pilot's Arder book in which each flight may be authorized.
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Approved- It is considered more strict supervision should be inforced at civilian operated schools.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Stress of circumstances and desire	should be inforced at civilian operated