

```
DUTY ON WHICH ENGAGED:
                                       COURT OF INQUIRY, INVESTIGATING OFFICER- LIFE PSHD USD
                                       OR COMMANDING OFFICER'S REPORT:
 Solo flight.
                                                 Commanding Officer's Report.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                                 1-11-40
                                       DATE:
                                       COMPOSITION:
 The aircraft came in to land with
                                                        F/L D.D. Atkinson.
 the drift, and the pilot failed to
check the ensuing swing. The right
                                             Commanding #11 E.F.T.S., Cap de la Madeleine.
wing hit the ground and the aircraft
                                                                                       P.Q.
                                       RECOMMENDATIONS:
 came to a stop on its engine,
                                                   Nil
PRIMARY CAUSE:
 The aircraft came in to land with
 the drift which resulted in the
 aircraft wringing; this wring was
 not checked in time and the re-
                                       ACTION TAKEN:
                                         (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
 sulting accident occurred.
                                             D.14 approved by A.M.T. 19211-40
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
                                                                      RECORDED BY
                                                                                         DATE
                                                                      CHECKED BY
                                つううううつうつ
```