

```
\mathcal{I}_{z}
DUTY ON WHICH ENGAGED:
                        Air to air firing COURT OF INQUIRY, INVESTIGATING OFFICER
                                              OR COMMANDING OFFICER'S REPORT:
 with camera gun.
                                                           COURT OF INCUIRY
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                              DATE:
                                                                13-12-40 to 28-12-40
                                              COMPOSITION:
THE AIRCROFT WAS TAKING OFF WHEN IT DEVELOPED
                                                              SQUADRON LEADER N.M. CARSCALLEN, PRESIDENT.
 A SLIGHT SWING TO THE RIGHT. THIS WAS
                                                              FLYING OFFICER E.V. MCKENZIE, MEMBER
                                                              FLYING OFFICER W. F.M. NEWSON. MEMBER.
OVERCORRECTED BY THE SECOND PILOT WHO THROTTLED
DOWN THE LEFT ENGINE TOO MUCH AND THE A/C
                                              RECOMMENDATIONS:
WENT INTO A VICIDENT SWING TO THE LEFT. BOTH
                                                                 IT IS RECOMMENDE THAT THE CAUSES OF THEIS
THROTTLES WERE THEN CLOSED AND THE A/C RAN OFF
                                                      ACCIDENT BE BROUGHT TO THE ATTENTION OF ALL PILOTS
THEE PAVED RUNWAY INTO A DITCH AND THE FUEE
                                                      FLYING THIS TYPE OF AIRCRAFT.
PRIMARY CAUSE: /SYSTEM WAS PUNCTURED AND THE
GASOLINE IGNITED BY FRICTION OR BROKEN WIRING
THE INTENSE HEAT CAUSED THE BOMBS IN THE
RACK TO EXPLOBE.
                    FULL RIGHT AND MODERATE
                                             ACTION TAKEN:
LEFT BRAKE WAS USED IN TRYING TO KEEP A/C
                                                (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
ON THE RIGHT PATH.
PRIMARY CAUSE: THE FAILURE OF THE FIRST
PILOT TO RETAIN PERONAL CONTROL OF THE
THROTTLES AT THE TAKE-OFF AND UNTIL AIRBORNE.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
POOR JUDGMENT ON THE PART OF THE SECOND
PILOT WHO MISHANDLED THE THROTTLES.
                                                                                  RECORDED BY
                                                                                                         DATE
                                                                                 CHECKED BY
                                                                                                         DATE
```