

/`	, , , , , , , , , , , , , , , , , ,	,,,,,,,,,,,	,,,,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICE	ER)
)	Taxiing	OR COMMANDING OFFICER'S REPORT:		
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	D-14	-
	Taxing on tarmac mechanic applied	COMPOSITION:)
)	brakes. Aircraft tipped over on			
)	its nose. Mechanic applied brakes			, 3
)	to avoid hitting an A/C which was passing directly in front of	RECOMMENDATIONS:		,
Ś	him.			3
<i>)</i>	PRIMARY CAUSE:	•		
	Mechanic's error in applying too			, ,
)	much brake.			.,
)		ACTION TAKEN)
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	IER	.)
)		NiL.		•)
))
)				· ')
.)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)	Break linings damp. A/C tipped			
<u> </u>	over on its nose.		RECORDED BY	DATE
,				
) `			CHECKED BY	DATE
))))))))))))))))))))))))