

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER			
Training.	OR COMMANDING OFFICER'S REPORT:			
·		D-12	+	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:			
Engine cut out on take-off, causing forced landing.	COMPOSITION:			
101004 14141116				
	RECOMMENDATIONS:			
PRIMARY CAUSE:				
Cold engine.				
	ACTION TAYEN			
	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other			
	NiL.			
SECONDARY CAUSE OR CONTRIBUTING FACTORS:				
Pilot should have warmed his				
engine more.	RECORDED	ВҮ		DATE
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED E	ΙΥ		DATE