

DUTY ON WHICH ENGAGED:

N.A.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Whilst towing A/C tractor skidded
on icy slope and collided with
A/C.

DATE:

COMPOSITION:

RECOMMENDATIONS:

Sufficient supply of calcium chloride to be kept
within the Unit at all times during freezing weather.

PRIMARY CAUSE:

1. Bad surface of aerodrome.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

2. Hitting obstructions.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____