

62	61	60	59	58	57	56	55	54	53	52	51	50	49	48	47	46	45	44	43	42	41	40	39	38	37	36	35	34	33	32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62																						
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																					
CAUSES OF ACCIDENTS																																																																																			
UNIT 12 E.F.T.S. Goderich		COM. 1		PLACE 7 miles S. of Goderich										DATE 8-4-43		TIME 1500																																																																			
A/C TYPE Tiger Moth 11		No. 3920		CRASH CAT. N.A.		SE		ME		DAY		NIGHT																																																																							
NAME		RANK		No.		DUTY		INJURIES		SERIOUS																																																																									
Gudgeon, R.		F/S		R96595		FI		Nil.		FATAL		INJURY																																																																							
Baldwin, E.W.R.		Lac.		R167327		PP		Nil.																																																																											
										CARD SERIAL N.		✓																																																																							
<i>Forced landing.</i>																																																																																			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																							
Tiger Moth 3920 N.A.												INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																															
G. Major 89200/N.A.												DUAL		SOLO		DUAL		SOLO																																																																	
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		STAGE OF FLIGHT																																																																							
NATURE OF ACCIDENT																																																																																			
UND'TD		PRIMARY		FL. CONTS.		MOV. SURFS.		STAB. SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UND'TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTS.		MISCEL.		UND'TD		PRIMARY		HAND.O.		MISCELLANEOUS		CAUSES		UND'TD		PRIMARY		TAXING		LANDING		TAKE-OFF		FLIGHT		STAIRY		FATAL		INJ.		3RD.		5th		4th		3rd		2nd		1st	

DUTY ON WHICH ENGAGED:

Sequences 19 - 10.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C force landed due to engine failure on starting a spin.

DATE:

D-14

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

54. Engine failure in the air.
Low idling speed together with atmospheric conditions on the day in question.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE