

J		.
		· • • • • • • • • • • • • • • • • • • •
,	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Training.	OR COMMANDING OFFICER'S REPORT: D-14.
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
)	Port fuel tank gauge stuck in full	COMPOSITION:
Ĺ	position, giving a false reading.)
,	Stbd. fuel tank was full.)
))
)		RECOMMENDATIONS:
)		Firstly, that a/c be refuelled and tanks checked after
`	DDIMADY CAUCE	each 2 hours flying. Secondly, that in the event of
)	PRIMARY CAUSE: 33. Technical defect.	engine failure, the fuel cock be switched over to the
)	oo. lecimical delect.	other tank at once.
))
)		ACTION TAKEN:
		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
)		NIL
))
)		
`	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	,
,	SECONDARI CAUSE OR CONTRIBUTING PACTORS:)
)		RECORDED BY DATE)
))
)	D.C. I. T. FORMAND DOG ASSESSMENT AND ADMINISTRA	CHECKED BY DATE
,)	R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CHECKED BY DATE
,	, , , , , , , , , , , , , , , , , , , 	