

Duty on which engaged:  Court of inquiry. Investigating Officer  Routine training flight. Practisingor Commanding Officer's Report:  D.14 #23  forced landings  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  DATE:	. <b>)</b> ) .
Routine training flight. PractisingOR COMMANDING OFFICER'S REPORT:  forced landings  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  DATE:	)
forced landings NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	,
	)
Noticed engine running rought, COMPOSITION:	
did cockpit check & noticed oil	,
pressure had dropped to zero so immediately cut throttle.	,
RECOMMENDATIONS:	
Expedite modified pump shafts for Ranger engine	
PRIMARY CAUSE: (C.O. states: - Imperative that immediate action	
taken or fatal accident will eventually result	·)
54. Engine failure in the air	
(Oil pump shaft broke at key way) ACTION TAKEN:	,
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	,
Nil	,
	)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
RECORDED BY	DATE
	,
CHECKED BY	DATE