

_/	1 1 Way 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		<u> </u>
/			J
)	DUTY ON WHICH ENGAGED:	OR COMMANDING OFFICER'S PERCET.	)
)	SOLO PRACTICE.	OR COMMANDING OFFICER'S REPORT:	7
`		COMMANDING OFFICER'S REPORT	
	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 27-1-41	,
)	PILOT BECAME LOST, AND IN A VERY STRONG WIND	COMPOSITION:	
)	OF 60 MILES AN HOUR, THE PLANE DRIFTED AWAY.	F/L E.A. WEAVER	)
)	A FORCED LANDING WAS SATISFACTORY. THERE		7
`	WAS NO DAMAGE TO THE AIRCRAFT.	RECOMMENDATIONS:	,
,		PUPIL PILOTS ADHERE STRICTLY TO THE FLYING REGULATIONS.	
)		IT IS RECOMMENDED THIS AIRMAN BE PUNISHED AND REPRIMANDED AND THIS	)
)	PRIMARY CAUSE:	REPRIMAND BE PLACED ON HIS CONDUCT SHEET.	)
)	THE PILOT BECAME LOST DUE TO CARELESSNESS IN		3
	ALLOWING THE PLANE TO DRIFT WHAY, IN WIND OF		,
,	60 MILES AN HOUR. THE BOUNDRY FOR SOLO FLYING	ACTION TAKEN:	)
)	WAS NOT ADHERED TO AND IS THE PRIMARY REASON	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
)	FOR THE PILOT BECOMING LOST.		
)		A.M.T. APPROVES D.14 8-2-41.	-
`			,
,			)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		)
)	Strong wind of 60 Miles an Hour		)
)		RECORDED BY DATE	)
`			,
)		CHECKED BY DATE	)
`			•