



DUTY ON WHICH ENGAGED: Forced landing  
practive.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT: ZLFM/AOP/PCDE/ET/MC

Commanding Officers Report.

IPHEL ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 27-2-41

COMPOSITION:

(B.J. Bouchier) Sqn. Ldr.

Long glide without warming engine plus continuing a forced landing approach, below 200 feet altitude without putting on engine. When throttle opened cold engine sputtered with result, pupil crashed through a wire fence.

RECOMMENDATIONS:

Severe disciplinary action for breech of flying regulations.

PRIMARY CAUSE:

Long glide without warming engine plus continuing a forced landing approach,

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_