

Τ			3
(2	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)
้า	Instrument flying - Seq. 19.	OR COMMANDING OFFICER'S REPORT:	
•		Commanding Officers Report.	
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 19-2-41	
)	Engine failed due to broken	COMPOSITION:)
)	crankshaft causing successful	(E.A. Weaver) Flight Lieutenant.	7
•	forced landing	SFE/AOPLES/IM/NK/	
•		RECOMMENDATIONS:)
)		The throttle should be opened and closed evenly	₁
)		and slowly, instead of sudden movements.	3
)	PRIMARY CAUSE:		3
•	Engine Failure.		
,)
)		ACTION TAKEN)
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)		(4, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2,)
3			
•)
J)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:) '
)	Broken Crankshaft.)
·)		RECORDED BY DAYE	
,			- ,
•)		CHECKED BY DATE)
)))))))))))))) [
_		The state of the s	