

/		33 <b>33333</b> 33333333333333	)
)	DUTY ON WHICH ENGAGED: Practicing forced	COURT OF INQUIRY, INVESTIGATING OFFICER	)
)	landings.	OR COMMANDING OFFICER'S REPORT:	JA
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officer's Report.  DATE: 24-2-41	.1
.)	Pilot allowed aircraft to reach	COMPOSITION: Flight Lieutenant L. B.B. Price.	)
)	a dangerousl* low altitude while	100.00	<b>)</b>
	practicing forced landings, and	ILCO/POM	
1	did not see contour of high mound of earth which he struck with port	RECOMMENDATIONS:	
)	lower mainplane as he opened the throttle. PRIMARY CAUSE:	Log book to be endorsed under CAP 100 Sed.4 para. 25 c.	<b>)</b>
			)
)	Disobedience of Flying Orders" Pilots are not to practice forced		)
)	landings or approaches except in		)
)	areas indicated by the instructor.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	эÈ-
)	When practicing forced aandings	(ii) Bloom Ellinini (b) Teanniane (b) O'MEN	)
)	the throttlw must be opened at a height of not less than 200 feet		3
•	above the ground."		<b>)</b>
``	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		7
•	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		)
•		RECORDED BY DATE	)
)		•	
.)		CHECKED BY DATE	) <u> </u>
)			)
		Lu Lu	