

```
DUTY ON WHICH ENGAGED:
                                       COURT OF INQUIRY, INVESTIGATING OFFICER
                                       OR COMMANDING OFFICER'S REPORT:
     Solo practice 10.17.22.
                                          COURT OF INQUIRY Monthly Accident Return.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                       DATE: 21-4-4]
                                       COMPOSITION:
Pilot attempted to turn down-wind
                                           President / S/L Voyce, J.B
too close to ground. Slipped in and
                                                      - S/L Mather, S.
                                           Member
broke undercarriage and right wing.
                                           Member
                                                      - F/L Ball.
                                       RECOMMENDATIONS:
                                                                1KCG/POL
                                                   NIL
                                                         Disciplinary action being taken.
PRIMARY CAUSE:
Inexperience on the part of the
pilot in low flying.
                                       ACTION TAKEN:
                                         (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
                                       Pilot LAC Crosse, found guilty of flying too low
                                       and damaging his aircraft and of carrying out solo
                                       flying in an unauthorised area, contrary to the
                                       provisions of Station Standing Orders
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
Aircraft hit ground from low height
                                                                      RECORDED BY
                                                                                           DATE
                                                                      CHECKED BY
```