

3		) ) ) ) ) ) ) ) )	12222 /2
<b>(</b> )	DUTY ON WHICH ENGAGED: Practice dual Flight	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:  The appractice landing by Pupil, the aircraft ran into a soft muddy rut o the aerodrome, causing it to turn on its nose a nd damaged the airscrew		M )
)	beyong repair.	RECOMMENDATIONS:	
)	PRIMARY CAUSE: Inexperience on part of the Pupil Pi	lot	3
<u> </u>		ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	) )
)			C
)			) .
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		)
)	Soft aerodrome surface.		) :
)		RECORDED BY	DATE
)	<u>, , , , , , , , , , , , , , , , , , , </u>	) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	DATE )