

)	DUTY-ON-WHIGH-ENGAGED:	COURT OF INQUIRY,	INVESTIGA	TING OF	FICER - ^			
)	OR COMMANDING OFFICER'S REPORT:							
,	Instructional flight NATURE OF ACCIDENT AND STAGE OF FLIGHT:		Comma	nding	Offic	er's Report		
	After taking off from airport and	DATE: COMPOSITION:	w 11 1	Dans and	1014 c	ht Lieutenant	•	
	climbing to an altitude of 500 ft.	COMITOSTITION.	Welle :	Drury,	t-18	ne Dregeenan	•	
	oil pressure failed. Pilot carried	•				•		
	out successful forced landing. No							
	damage was caused to aircraft or	RECOMMENDATIONS:						
	property.							
	PRIMARY CAUSE:		•					
	Seizure in # 2 cylinder caused							
	engine to smoke and lose revolution	8.						
		ACTION TAKEN:						
		(A) DISCIPLINARY	(B) TECHN	ICAL (C	OTHER			
This engine was replaced by a new one.								
		J			·	· · · · · · · · · · · · · · · · · · ·		
	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		•					
					RECOF	DED BY	DATE	