

```
DUTY ON WHICH ENGAGED:
                                        COURT OF INQUIRY, INVESTIGATING-OFFICER
                                        OR COMMANDING OFFICER'S REPORT:
                                                  Commanding Officer's Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                       · DATE:
                                                  17-4-51 more of Tables Comment
In making a landing, pupil landed in COMPOSITION: E.A. Weaver, Flight Lieutenant.
upwind area of aerodrome, applied
                                                     LM/ANT/FOM
brakes too quickly causing aircraft
to go up on its nose breaking airscrew
and then falling back to normal
                                        RECOMMENDATIONS:
position.
                                         Instructor in this case allowed pupil to land more
                                        than half way up the aerodrome with no corrective measures being used. Instructors in all instances where dual flying is being carried out should be
PRIMARY CAUSE:
Error in judgment on part of pupil
                                        alert and ready to correct any error that a pupil
and instructor.
                                        may make before an accident or damage occurs to an
                                        aircraft.
                                        ACTION TAKEN:
                                           (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
Too harsh application of brakes, causing
                                                                       RECORDED BY
aircraft to go up on its nose.
                                                                       CHECKED BY
                                                                                             DATE
```