



DUTY ON WHICH ENGAGED:

Solo take-off and landing practice.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT: LH/ATO/PSMD

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Solo pupil did not check drift after bad bounce during poor landing causing a/c to ground loop and turn over on its back.

DATE:

Monthly Accident Return.

COMPOSITION:

RECOMMENDATIONS:

Further dual instruction in take-offs and landings.

PRIMARY CAUSE:

Bad landing by recent solo pupil.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Right wing tip touched the ground after subsequent ground loop.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_