

TYPE SOLO OR TYPE.
DUTY ON WHICH ENGAGED:

First solo on type.
Circuits and landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft landed with undercarriage retracted.

PRIMARY CAUSE:

Carelessness, inexperience.
In that pupil failed to check vital actions prior to landing when completing first solo.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Landing aircraft with the u/c up.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

DATE:

Monthly Accident Return.

COMPOSITION:

LUC/PEL/UF/UEDL

RECOMMENDATIONS:

1. Log Book entry "Carelessness".
2. Admonished.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____