

))))))))))))))))))))))))))))))))))))
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	•
BOMBING EXERCISE	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FL		
FORCED LANDING EXECUTED FROM 6000 I	/ W/79F/25 3/229/25/3	<u> </u>
ROD.		
	RECOMMENDATIONS:	
PRIMARY CAUSE:		
ENGINE FAILURE DUE TO BROKEN CONNEC	TING	
ROD		
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	,	
SECONDARY CAUSE OR CONTRIBUTING F	ACTORS:	
SUCCESSFUL FORCED BANDING	RECORDED BY	DATE
	CHECKED BY	DATE
))))))))	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\))))
