

DUTY ON WHICH ENGAGED:

FLYING INSTRUCTION

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

WHILE DEMONSTRATING FORCED LANDINGS THE INSTRUCTOR CLOSED THE THROTTLE, CUTTING OUT THE ENGINE AND NECESSITATING A REAL FORCED LANDING. IN LANDING THE PILOT UNDERSHOT THE FIELD, STRUCK A FENCE AND OVERTURNED

DATE:

COMPOSITION:

FM/AOF/PCDE/ES/PA/MC/T

RECOMMENDATIONS:

PRIMARY CAUSE:

PILOT CLOSED THROTTLE, CUTTING OUT ENGINE AND NECESSITATING FORCED LANDING

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Endorsation of Sgt. Rideout's Logbook
in accordance with C.A.P, 100

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT STRUCK A FENCE WITH THE UNDERCARRIAGE WHILE LANDING AND TURNED OVER

RECORDED BY

DATE

CHECKED BY

DATE