

()))))))))))))))))))))))))))))))
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
SOLO PRACTICE	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	R.170
LANDING VERY NEAR AIRCRAFT WAS XXXXXIG IMMARD ANOTHER	DATE: COMPOSITION: L 5/P55
AIRCRAFT - PILOT TRIED TO VEER AWAYA	- -
AND GROUND LOOPED	
	RECOMMENDATIONS:
PRIMARY CAUSE:	
INEXPERIENCE OF PILOT CAUSED GROUND	
LOOP WHELE TAXIING	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Instructors and students lectured
	on safety rules pertaining to such cases as this.
SECONDARY CAUSE OR CONTRIBUTING FACTORS: PILOT SHOULD HAVE MADE ANOTHER CIRCLE INSTEAD	•
OF LANDING WHEN AVOIDING ANOTHER AIRCRAFT	RECORDED BY DATE
	Walter and the same and the sam
	CHECKED BY DATE
)))))))))))))))))))))))))