

/			
2	,,,,,,,,,,,,,,,))))))))))))))))))))	Ð
<u></u>	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	3
3		OR COMMANDING OFFICER'S REPORT:	البري
·)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 27 7-43	,
)		COMPOSITION: 27-7-41 FS/A & P/PCDE/ES/PM/PA	W.
)	ENGINE FAILED TO RESPOND	Brumagin, C.R.	7
5		or many cont)
.)		RECOMMENDATIONS:)
·:):		Must the Dilette Lee Beats he endered for	الاستخار ب
	ODIMADY CAUCE.	That the Pilot's Log Book be endorsed for "Error in judgment")
٠,	PRIMARY CAUSE:	Ter Ar Try Janapassa	3
\mathbf{O}	ENGINE FAILED AT 100 FEET		•
.			
)		ACTION TAKEN:	7
·		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	3
)		wil .)
)			3
O		1	
0	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
J	PILOT FORCE LANDED IN BAY OF QUINTE		زو
)		RECORDED BY DATE	-
<u> </u>	•)
<i>)</i>		CHECKED BY DATE)
<u> </u>	$\mathcal{O}(\mathcal{O}(\mathcal{O}))$))))))))))))))))))) 	3