

(3)))))))))))	••••••••••••••••••••••••••••••••••••••
DUTY-ON WHICH ENGAGED: CO	OURT OF INQUIRY, INVESTIGATING OFFICER
	COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: DAT	TE:
and round round ratio Tuks Sciidant	MPOSITION: IL CG/PSF/N/N/CN
) descended too low into rough field.  After striking ground the a/c bounced and landed on its nose and starboard	•
) wing. Aircraft completely burned.	COMMENDATIONS:
	Disciplinary action recommended.
Decending too low into roughtfield.	) )
	TION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  O
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	)
Aircraft struck rough field heavily distorted the centre section and	, , , , , , , , , , , , , , , , , , ,
gasoline tenk sufficiently to dis-	RECORDED BY DATE
connect the fuel line, allowing gasoling to contact the hot engine and exhaust.	CHECKED BY DAYE DAYE