

3	DUTY ON WHICH ENGAGED:		3 3 3 4 0
	Practicing Sequences	COURT OF INQUIRY, INVESTIGATING OFFICER	
•	Fracticing Sequences	OR COMMANDING OFFICER'S REPORT: R.170	#7 ***
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:)
)	After normal landing and rolling	COMPOSITION: 45/755/055	•
)	50 yards aircraft turned to right.	•	• • • • • • • • • • • • • • • • • • •
•	Opposite rudder did not correct swi	•)
	and the aircraft ground looped, bre		
)	king spars in port lower main plane and collapsing undercarriage.	RECOMMENDATIONS:	·) :
)	and collaboling aimel callinge.		a !
)	PRIMARY CAUSE:	61 Z: 37	3
)	The aircraft ground-looped to right		ا المساور
\mathcal{C}	while rolling to a step after landi	mR•	
		ACTION TAKEN:	.
-5		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	.
))
))
)	,		
\mathbf{O}	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		,
Š	The port wing struck the ground, br	80.	3
ر ۱	king both spars in the lower port w		DATE)
, ,	and collapsing the undercarriage.		÷ .
)		CHECKED BY	DATE J
)))))))))))))))))))	3))))))]]]]]]]]	3 A A A A