

### OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

### ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
4.3.42	"CBI"	Im. S Dapoc Aerod.	1150	5B745s A 8	5/3	3/0 Grant Cook			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

### AIRCRAFT RECORD CARD

PAT'D 1920

#### REMARKS

24/3/43 - Allotted # 987 for gun turret installation

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT	<i>Aircraft Repair Ltd, Edmonton</i>	DATE	<i>7/4/41</i>	TRANSFER ORDER No.	<i>77</i>
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>13.5.41</i>	<i># 2 T.C. # 5 Bt 8 Schl</i>	<i>T.O. 1656</i>			
<i>26.1.43</i>	<i>Co. J. Keenan # 270</i>	<i>T.O. 4883</i>			
<i>24.3.43</i>	<i>FRD St Johns Island</i>	<i>TO 1611</i>			
<i>23-5-44</i>	<i>Apdal. # 2 T.C.</i>	<i>T.O. 13415</i>			
<i>1.12.44</i>	<i>SPDA No. 2 AIR COMMAND</i>	<i>T.O. 17327 (1)</i>			
<i>16.2.45</i>	<i>War Assets Corporation</i>	<i>T.O. 18604</i>			

REMARKS  
 HRS:-  
 SINCE NEW:- *488.25*  
 SINCE OVERHAUL:-  
 LOCATION:- *3 Bt 8.*

U.K. CONTRIBUTION.

ENGINE TYPE	<i>MERLIN III</i>	UNITS	<i>1</i>	AIRSCREW TYPE (CODE)		REF. No	<i>5205/8433</i>
BATCH No.	<i>TP 1</i>	QUAN. IN BATCH	<i>1</i>	LEDGER FOLIO	<i>1200-38-1</i>	SPECIFICATION No.	
REGISTRATION No.	<i>1923</i>	MAKE & MODEL	<i>BATTLE I</i>	YEAR	<i>1941</i>	TYPE	<i>S E CREW TRAINER</i>
			<i>SOLD</i>			MANUFACTURERS No.	<i>R 3947</i>