

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
25.5.43	Repair <sup>to nose</sup> wheel	W. Rea + 3 R.D.					
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

REMARKS

16.5.43 - aircraft struck by MT vehicle 32636 at #305 m.  
 Root of truck struck the starboard float of  
 A/C causing damage amounting to £85.61.  
 Ref 1600-32-636-2

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT FF 13 A. I. D Vancouver 11/2 DATE 18.2.43 TRANSFER ORDER No. 5699

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
1-4-43	H.A.B	T.O. 6213			
30.12.44	(C.O. 21)	T.O. 1502			
25.5.45	W. Res # 3 R.D.	T.O. 1582			
8.8.45	Stand Reserve 2nd C	T.O. 14396			
11-10-45	Stand Reserve WAC	T.O. 15372			
27-11-45	Stand Reserve MC (20005) to MC 15885				
17-1-46	opdel MC 7 REMOVED TO MC 16282				
3-2-46	War Assets	10 MC 13069			

REMARKS 18/2/43:- HELD UNTIL RADIO EQUIPMENT IS INSTALLED.  
 1.4.43 40 amended to read 5168  
 11.10.45 - Serviceable  
 Time since new - 1056:00  
 ✓ ✓ 01h MA

30/8/44:- ON LOAN FROM W.H.O. TO B.C.A.T.P.  
 Purchased  
 CP 350851/20317  
 11/1/407/20228

ENGINE TYPE	WASP SIC36	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	CD 364	LEDGER FOLIO	700-38-173	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.			
8762	CANSO A (AMPHIBIAN)	1943	T E BOMBER				